ULTRATRONIK

QUICK START GUIDE FOR 411-121.000S

These instructions support you during setting up the display-set so that you can quickly start your development.

cable connection
optional cable connection
not included
connect last
Connectors/adapters

411-121.000S



Please follow the precautions of HMI touch module and Interface card.

- Read this manual and safety regulations carefully before using the product.
- Only use delivered accessory parts

Take care to plugin cables and adapters correctly

- Keep contacts in the right position
- Align components before tightening
- Close stiffener correctly

Please connect to power supply as last!
Make sure to turn off power supply before dis-/connecting components

Contact us if you require any service or assistance at displays@ultratronik.de
Please include the following information:

- Company name
- Your name
- Company address
- Email
- Telephone
- Exact description of the hardware, etc.
- Exact description of the software used (for example: Win XP with driver XYZ)
- Exact description of the error

Error and omissions excepted – Observe notice of protected rights in accordance to DIN34 / ISO16016