



QUICK START GUIDE FOR 411-051.000S

These instructions support you during setting up the display-set so that you can quickly start your development.



411-051.000S



Please follow the precautions of HMI touch module and Interface card.

- Read this manual and safety regulations carefully before using the product.
- Only use delivered accessory parts

Take care to plugin cables and adapters correctly

- Keep contacts in the right position
- Align components before tightening
- Close stiffener correctly



Please connect to power supply as last!
Make sure to turn off power supply before dis-/connecting components

Contact us if you require any service or assistance at displays@ultratronic.de

Please include the following information:

- Company name
- Your name
- Company address
- Email
- Telephone
- Exact description of the hardware, etc.
- Exact description of the software used (for example: Win XP with driver XYZ)
- Exact description of the error